

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

EI679  
WSW  
1/2-1  
0.987 mi.  
5210 ft.

MANHOLE #71776  
WEST 29TH ST/NESURF AVE  
BROOKLYN, NY

NY Spills S106469659  
N/A

Site 1 of 5 in cluster EI

Relative:  
Higher

Actual:  
4 ft.

SPILLS:

Name: MANHOLE #71776  
Address: WEST 29TH ST/NESURF AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0402391 / 2004-09-14  
Facility ID: 0402391  
Facility Type: ER  
DER Facility ID: 258905  
Site ID: 321388  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2004-06-02  
Investigator: SKARAKHA  
Referred To: Not reported  
Reported to Dept: 2004-06-03  
CID: 407  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2004-06-03  
Spill Record Last Update: 2004-09-14  
Spiller Name: ERT DESK  
Spiller Company: CON EDISON  
Spiller Address: 4 IRVING PLACE  
Spiller Company: 999  
Contact Name: ERT DESK  
DEC Memo: "e2mis no 153668 DELAROSA, EMP NO. 19655 FOUND APPX 1 PT OF UNKNOWN OIL ON APPOX 300 GALS OF WATER. NO SEWERS OR WATERWAYS AFFECTED. HE WAS UNABLE TO VERIFY ANY SUBSTANTIAL CRACKS IN THE STRUCTURE, THE SOURCE OF THE SPILL OR IF THERE WAS ANY OIL FILLED EQUIPMENT INVOLVED. ONE LIQUID SAMPLE WAS TAKEN. CLEANUP PENDING RESULTS. Lab Sequence Number: 04-04314-001 PCBs < 1 ppm. BROOKLYN ENV OPS O/S B. BROWN REPORTS THAT CLEANUP IS NOT EXPECTED TO BE COMPLETE PRIOR TO 18:20 HRS. DUE TO AMOUNT OF WORK REQUIRED TO CLEAN STRUCTURE AND ALSO DUE TO CABLE AND UNDERGROUND CREWS CURRENTLY WORKING IN STRUCTURE. Update - 6/3/04 - 2015hrs Sam Rosenking, env. ops mech reports double washed structure with bulldog. Found cement sump in structure. Removed all liquids with vactor. Structure not making water at this time. No leaking co. equipment found. Removed env. stop tag # 39231. Clean up completed 100 ."

Remarks: "Spill is 1 pint into 300 gallons of water. "

All Materials:

Site ID: 321388  
Operable Unit ID: 884076  
Operable Unit: 01

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material ID: 490012  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported